

PR-1

	Name of indicator	Norm	Actual value
1.	Appearance	Crystalline white mass	Crystalline white mass
2.	The melting temperature, °C	Not lower than 52	53.2
3.	Mass fraction of oil, %	Not more than 0,80	0,69
4.	Color, conventional marks	Not more than 4	2
5.	Smell	None	None
6.	Benz a pyrene content	None	None
7.	Mass fraction of sulfur, %	None	None
8.	Mass fraction of water, %	None	None
9.	Mass fraction of mechanical impurities, %	None	None
10.	The content of water soluble acids and alkalis	None	None
11.	Phenol content	None	None
12.	Furfural Content	None	None
13.	The pour point determined by the method of a rotating thermometer, ° C	-	52.8
14.	Density at 70 ° C, g/cm	-	0.769
15.	The value of the penetration of the cone at 25 °C, 0,1 mm	-	11

