

PR-4

	Name of indicator	Norm	Actual value
1.	Appearance	Homogenous mass without noticeable foreign matter from white to light yellow	Match
2.	The melting temperature, °C	Not lower than 46	53,4
3.	Kinematic viscosity at 100°C, mm ² /c	Not more than 6	4,1
4.	Water content, %	None	None
5.	Mass fraction of oil, %	Not more than 15	4,4
6.	Saybolt color	Not more than plus 5	Plus 20
7.	Magnitude of penetration by a cone at 25°C, 0,1 mm	-	14
8.	Mass of mechanical impurities %	≤ 0,1	0,06
9.	Density at 70°C, g/sm ³	-	0,782
10.	Freezing point, determined by the rotating thermometer	-	52,0
11.	Magnitude of penetration by a cone at 25°C, 0,1 mm	-	16

