

PR-7

	Name of indicator	Norm	Actual value
1.	Appearance	Homogenous mass without noticeable foreign matter from white to light yellow	Match
2.	The melting temperature, °C	Not lower than 46	52,6
3.	Kinematic viscosity at 100°C, mm ² /c	Not more than 6	4,017
4.	Water content, %	None	None
5.	Mass fraction of oil, %	Not more than 15	5,8
6.	Saybolt color	At least plus 5	Plus 20
7.	Magnitude of penetration by a cone at 25°C, 0.1mm	-	14
8.	Mass of mechanical impurities, %	Not more than 0,1	0,08
9.	Density at 70°C, g/sm ³	-	0,776
10.	Freezing point, determined by the rotating thermometer	-	49,0
11.	Magnitude of penetration by a cone. At 25°C, 0.1mm	-	14

